



7505669

Grease Interceptor Report

Installations, Maintenance and Cleaning

Account

Account Monzo Burger Date of Service 03/04/2026 Time 10:00h  
 AHJ (Authority having jurisdiction) Dan Chau Service Interval Annually  Quarterly  Bi-Annually  Monthly   
 Address Line 1 1401 Granville St Inspection Yes  No  Cleaned Yes  No   
 Address Line 2 \_\_\_\_\_ Manufacturer NA  
 City Vancouver Province BC Postal Code V6Z1n1 Model(s) NA  
 Phone (Business) (604) 225-8107 Size (Gallons): 150  
 Phone (Mobile) \_\_\_\_\_ Total Liquid Collected 151  
 Fax \_\_\_\_\_ Interceptor Location Kitchen Floor

Mark appropriate:  Pass  Fail. All FAIL answer shall be explained in comments. All failures shall be the responsibility of the authority having jurisdiction to repair or replace at their expenses. Any additional repair costs are not included with this inspection, unless otherwise stated.

Pre-Service

--

Answers / Comments

Grease Interceptor is accessible to service	Pass <input checked="" type="checkbox"/> Fail <input type="checkbox"/>	Approx. percentage of grease & solids in relation to the Grease Interceptor.
Inspected condition of the Grease Intereceptor before service	Pass <input checked="" type="checkbox"/> Fail <input type="checkbox"/>	
Grease Inteceptor is functional prior to service.	Pass <input checked="" type="checkbox"/> Fail <input type="checkbox"/>	
FOG's do not consume more than 25% of the Interceptor (If fail recommend increasing service intervals)	Pass <input checked="" type="checkbox"/> Fail <input type="checkbox"/>	
There are no leaks found in the Grease Interceptor(s)	Pass <input type="checkbox"/> Fail <input checked="" type="checkbox"/>	
Condition of the gaskets and seals	Pass <input checked="" type="checkbox"/> Fail <input type="checkbox"/>	

After Service

Grease Interceptor has been properly cleaned	Pass <input checked="" type="checkbox"/> Fail <input type="checkbox"/>
Rate of flow is sufficient	Pass <input checked="" type="checkbox"/> Fail <input type="checkbox"/>
Condition of the Grease Interceptor after service	Pass <input type="checkbox"/> Fail <input checked="" type="checkbox"/>
Any issues have been reported to the AHJ	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
Service tag has been issued or updated	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>
Location of service tag:	
Is a return visit required to complete repairs?	Yes <input checked="" type="checkbox"/> No <input type="checkbox"/>

Notes: - Grease interceptor has multiple holes in the bottom of the unit. Recommend replacing the unit with a Plastic GI, as rust and water easily corrode the unit.

I state that the information on this form is correct at the time and place of inspection. All equipment was tested in conformance with applicable codes equal to or beyond manufacturer specifications. At the time indicated above, equipment inspected or serviced was left in operational condition except as noted in comments. I understand that under municipal city bi-law a copy of this report is to remain on premises for a period no less than 2 years.

Owner/Authorized Agent: Dan Chau Date: 03/04/2026 Technician: Alex J. Collins

© 2026 Grease Ducks Ltd. All rights reserved



March 4, 2026

